

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1309
West
> 1
1.669 mi.
8813 ft.

MH #TM2357
SURF AVE & 50TH ST
BROOKLYN, NY

NY Spills S103828222
N/A

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: MH #TM2357
Address: SURF AVE & 50TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9813880 / 2007-05-03
Facility ID: 9813880
Facility Type: ER
DER Facility ID: 72993
Site ID: 78435
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-02-16
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 1999-02-16
CID: 366
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False

Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-02-16
Spill Record Last Update: 2007-05-03
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo:

"05/03/07 - See e-docs for Con Ed report detailing cleanup and closure. Prior to Sept, 2004 data translation this spill Lead_DEC Field was ENGELHARDT DEC inspector notes: 2/16/99, 1419 hrs: ERT Kessler - about 1 pint oil. Leak at top of unit - air leaking now but no oil. May also be leak at bottom. Tested 2 weeks ago - 101 ppm PCBs. Clean up in progress. EPA # was issued. Drains, sumps cemented over. e2mis no. 123-047: M. ADAMO #28458 REPORTS UNDIAPERABLE SHEEN (1 PINT) 50 GALLONS OF WATER IN TM2357 N/S SURF AVE 27' WEST OF BEACH 50 ST. PRESSURE TESTED UNIT -- UNIT LEAKING PRESSURE FROM TOP OF UNIT BUT NO OIL LEAKING FROM TOP OF UNIT. SUMP PIT IN STRUCTURE APPEARS TO BE CEMENTED. CANNOT TAKE OIL LEVEL READING UNTIL WATER REMOVED FROM STRUCTURE. OIL SAMPLE WAS TAKEN FROM UNIT 1 WEEK AGO - PCB READING AT THAT TIME WAS 101 PPM AS PER MR ADAMO.- OIL SAMPLE WAS TAKEN BECAUSE EXISTING UNIT IS A 300KVA UNIT & WE WERE GOING TO REPLACE IT WITH A 500KVA UNIT - IN ORDER TO TRANSPORT OLD UNIT WE MUST HAVE A PCB READING FOR THAT UNIT. OVER 50 TANKER ORDERED TO REMOVE WATER FROM STRUCTURE. SAMPLE TAKEN AND E.S.TAG#8234 PLACED. NO SEWERS OR WATERWAYS AFFECTED. LAB RESULT FROM 2/11/99 - 99-01414. 101 PPM. UPDATE 2/16/99 1220HRS. TONY LOSCHIAVO O.S.OF EQUIPMENT GROUP REPORTS BOTTOM OF SUMP PIT HAS NO BOTTOM. MR. LOSCHIAVO ALSO STATES OIL IS

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

LEAKING FROM BOTTOM OF TRANSFORMER. EQUIPMENT GROUP WILL DIG OUT APPROPRIATE AMOUNT OF SOIL AND CEMENT SUMP. UPDATE 2/16/99 16:10 HRS -- ADAMO REPORTS UNIT DRAINED AND REMOVED. FLUSH & TANKER ON LOCATION, THEY WILL COMPLETE CLEANUP AND SEAL THE PIT. UPDATE: 2/16/99 - 2000 J. DEKANCHUK - O.S. - ENV. OPS., REPORTS 101 PPM CLEANUP COMPLETE DOUBLE WASHED STRUCTURE WITH BIO GEN 760 AND TAG #8234 REMOVED. OVER 50 PPM CLEANUP PAPERWORK RETAINED WITH ENV. OPS. " Not reported

Remarks:

"CALLER REPORTING AN UNKNOWN AMOUNT OF OIL WAS FOUND IN MANHOLE. SAMPLES WERE TAKEN AND CLEAN UP PENDING RESULTS. CON ED #123047."

All Materials:

Site ID: 78435
Operable Unit ID: 1074604
Operable Unit: 01
Material ID: 310588
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported